














 <p><b>150-4002</b> Blower Motor OE# 1699291-C1, 2500485-C1</p>	 <p><b>150-4103</b> Blower Motor OE# 1699949-C1</p>	 <p><b>150-4021</b> Blower Motor OE# 3542611-C2, BOA80 415 00 879</p>	 <p><b>OE Sanden</b> <b>300-4377</b> Aftmkt 300-4379 OE# 3547916-C1, 3628699-C1, 4546, 4815</p>
 <p><b>OE Sanden</b> <b>300-4378</b> Aftmkt 300-4380 OE# 3547917-C1, C91; 3628700-C1, 4816</p>	 <p><b>OE Sanden</b> <b>300-4388</b> Aftmkt 300-4390 OE# 3582435-C1, 4418</p>	 <p><b>350-2011</b> Condenser OE# 2505650-C92, 2586812-C91</p>	 <p><b>350-2012</b> Condenser OE# 2508698C-91, 1E-5114</p>
 <p><b>350-2017</b> Condenser OE# 2591836-C91, 2594898-C91, 1E-5993</p>	 <p><b>450-6550</b> Expansion Valve OE# 1696846-C1, 2503783-C91</p>	 <p><b>450-6552</b> Expansion Valve OE# 1699955-C2, 2501794-C91</p>	 <p><b>450-6560</b> Expansion Valve OE# 3660853-C2, 324353, 324553T</p>
 <p><b>800-1900</b> Accumulator OE# 3542577-C2, BOA80 232 00 139</p>	 <p><b>825-3980</b> Receiver Drier OE# 3670134-C1</p>	 <p><b>825-4425</b> Receiver Drier OE# 2000821-C1, 1693117-C1</p>	 <p><b>850-9323</b> Thermister OE# 3548043-C1; C2, 3622764-C1</p>